

SAS Superstructure

Location: 04-SF-80-13.2 / 13.9 Client Name: CalTrans

Daily Diary Report by Bid Item

Contract No.: 04-0120F4

Diary #: 532 Const Calendar Day: 954 Date: 19-Apr-2012 Thursday

Inspector Name: Daouk, Sami Title:

Inspection Type: Continuous

Shift Hours: 07:00 am 06:30 pm **Break:** 00:30 **Over Time:** 03:00

Federal ID: Location:

Reviewer: Schmitt, Alex Approved Date: Status: Submit

Weather

Temperature 7 AM 12 PM 4PM

Precipitation Condition Rain

Working Day If no, explain:

Diary:

Cable Compaction

ABF crews came to the site at 6:50 AM. Crews had to work on the South main span cable compaction . They started at 7:00 AM.

Obra, Carlos, Jeffery, Mario, & Roger had to work on the cable compaction. Crews had to prepare their tools, equipments, bring materials to the site, & connect the power line. They were done at 7:15 AM. They started to compact at 7:20 AM. Crews had to compact between panel plates # 44 & 46. They had to back the compaction machine 3 meters toward the saddle to re-compact the cable to reduce the size of the width, install new straps, & remove the loose straps. Crews were done at 12:00 PM.

In the afternoon, crews continued to compact the cable, install nylon straps, measure the cable, release the jacks pressure, re-compact, remeasure the cable, install stainless steel straps, & remove the nylon straps. They started at 12:40 PM.

At 2:00 PM. one of the hydraulic fitting leaked hydraulic oil. Crews had to stop , clean the jack , & call the technician . The hydraulic leak was repaired . Following the same procedures as previous locations . Crews resumed compacting at 2:30 PM.

At 4:00 PM. crews had to work on the outer strands. They had to cut & remove the tape for 10 meters strip ahead of the compaction machine. They were done at 4:30 PM. Crews compacted the last location for today at panel point 46 at 5:50 PM. They were done at 5:00 PM. Crews had to wrap up their tools & equipments. They left at 5:10 PM.

ABF engineers & I had to measure the height & width of the cable between PP 44 - 5 to PP 44 - 12. Height range 781 mm. - 786 mm Width range between 797 mm. & 801 mm.

Due to full time inspection . I had to work on my reports for Wednesday & Thursday . I was done at 6:30 PM.

04-0120F4	Bid Item: 067	C-PWS-SUC.067	Compact Suspension Cables					
AMERICAN BRIDGE/FLUOR, A JV								
Labor								
Trade	Class	Name	RT Hrs O	T Hrs	DT Hrs	Total Rem	narks	Dispute
Contractor:	AMERICAN BRIDGE/FLUOR, A JV							
Ironworker	JNM	ROGELIO RUIZ	8.00	2.00	0.00	10.00		
Ironworker	FOR	OBRA PAULK	8.00	2.00	0.00	10.00		
Ironworker	APP	MARIO MARQUEZ	8.00	2.00	0.00	10.00		
Ironworker	JNM	JEFFERY STEWART	8.00	2.00	0.00	10.00		
Ironworker	JNM	CARLOS BUSTAMANTE	8.00	2.00	0.00	10.00		



Page 1 of 2

Run date 22-Nov-14

04-0120F4

04-SF-80-13.2/13.9

Self-Anchored

Suspension Bridge

Time 12:08 AM

Daily Diary Report by Bid Item

Job Name: 04-0120F4 Inspector Name Daouk, Sami Diary #: 532 Date: 19-Apr-2012 Thursday

